

Seakamp replacement

200420

zinc

Any idea what is the zinc matching the Seakamp 200420 heat exchanger?

Seakamp just replied to me "1/4 npt thread zinc is 1.7 inch"

Checking on the catalina36.org association, I got recommended size E0 from this site.

▪ <http://www.boatzincs.com/engine-sizes.html>

They also have a page for the kind you screw into the brass cap – but you may have to cut that to length.



Anyway I had to cut to the length even the E0, as soon as it was inserted the water was not able to go through anymore.