

# AC circuit corroded bus bar replacement

One of the item to tackle from our purchase survey! The original bus bar for the AC circuit was corroded. It was a straight forward maintenance.

Less of \$20 bus bar from blue sea and some jumpers.













